

FIELD TEST SOFTWARE NOTICE

This report has been generated using a controlled field-test version of Smokevent Pro Suite. The inspection, service, remedial or site information shown in this public sample has been replaced with demo data and generic asset imagery. The platform is currently available for private demonstrations and selected field-test partners while prepared for wider release.

Customer Details

Customer: Demo Property Management Ltd**Site:** Demonstration Building**Address:** Demo address - public sample**Job Number:** DEMO-INS-0001**Inspection Date:** Demo date**PDF Generated:** Demo date**LIFE SAFETY SYSTEM CURRENTLY OPERATIONAL**

All recorded assets have been marked GREEN at the time of inspection. Based on the recorded inspection results, the smoke ventilation system appears to be in working condition at the time of testing.

Report Summary

24

Total Assets

24

Green

0

Amber

0

Red

24Assets With
Photos**0**Flow Rate
Readings**0**

Phase Readings

0

Battery Failures

0

Remedial Actions

Engineer Sign-Off Confirmation

The following confirmation records the engineer's testing declarations, job summary, engineer name and signature for this public demo report.

INSPECTION CONFIRMATION

INSPECTION/TEST COMPLETED?

Yes

FIRE ALARM INPUT TESTED?

Yes

SMOKE DETECTOR TEST?

N/A

SYSTEM LEFT OPERATIONAL?

Yes

COMPLETED AT

Demo date

SITE / VISIT SUMMARY

SITE / VISIT SUMMARY

Demo inspection summary. The smoke ventilation system was reviewed as part of a public sample report. Recorded assets are shown as operational for demonstration purposes, with evidence and asset details presented in a consistent report layout.

SIGN-OFF ENGINEER

SIGN-OFF ENGINEER

Demo Engineer

DATE SIGNED

Demo date

ENGINEER SIGNATURE

Redacted public sample



Smoke Ventilation Inspection Report

Final Client Inspection Report

Demo Contractor Ltd

Smoke-control reporting sample

support@smokeventpro.com

www.smokeventpro.com

Office Sign-Off

Name: Demo Office Reviewer

Date: Demo date

Office Signature

Redacted public sample

Asset Register By Building

The exchange

Demo building

Asset ID	Type	Floor	Area	Condition	Photos	Battery Readings	Vent Flow Rate	Phase Readings
STS1	Control Panel	First	Stuart hall room	Green / Operational	2	N/A	N/A	N/A
STS2	Break Glass	Second	Core 1 lobby	Green / Operational	1	N/A	N/A	N/A
STS3	AOV Damper	Second	Core 1 lobby	Green / Operational	1	N/A	N/A	N/A
STS4	AOV Damper	Second	Core 1 head of stairs	Green / Operational	1	N/A	N/A	N/A
STS5	AOV Damper	First	Core 1 lobby	Green / Operational	1	N/A	N/A	N/A
STS6	Break Glass	First	Core 1 lobby	Green / Operational	1	N/A	N/A	N/A
STS7	Break Glass	Ground	Core 1 lobby	Green / Operational	1	N/A	N/A	N/A
STS8	AOV Damper	Ground	Core 1 lobby	Green / Operational	1	N/A	N/A	N/A
STS9	Fan	Roof	Core 1	Green / Operational	1	N/A	N/A	N/A
STS10	Fan	Roof	Core 1	Green / Operational	1	N/A	N/A	N/A
STS11	Control Panel	Second	Core 2 stairs	Green / Operational	2	N/A	N/A	N/A
STS12	AOV Damper	Second	Core 2 head of stairs	Green / Operational	1	N/A	N/A	N/A
STS13	Break Glass	Second	Core 2 lobby	Green / Operational	1	N/A	N/A	N/A
STS14	AOV Damper	Second	Core 2 lobby	Green / Operational	1	N/A	N/A	N/A
STS15	AOV Damper	First	Core 2 stairs	Green / Operational	1	N/A	N/A	N/A

Asset Register By Building Continued

The exchange continued

Demo building

Asset ID	Type	Floor	Area	Condition	Photos	Battery Readings	Vent Flow Rate	Phase Readings
STS16	AOV Damper	First	Core 2 lobby	Green / Operational	1	N/A	N/A	N/A
STS17	Break Glass	First	Core 2 lobby	Green / Operational	1	N/A	N/A	N/A
STS18	AOV Damper	Ground	Core 2 lobby	Green / Operational	1	N/A	N/A	N/A
STS19	Break Glass	Ground	Core 2 lobby	Green / Operational	1	N/A	N/A	N/A
STS20	AOV Damper	Second	Core 1 head of stairs	Green / Operational	1	N/A	N/A	N/A
STS21	Damper	Roof	Core 1	Green / Operational	1	N/A	N/A	N/A
STS22	Damper	Roof	Core 1	Green / Operational	1	N/A	N/A	N/A
STS23	Smoke Detector	Roof	Core 1	Green / Operational	1	N/A	N/A	N/A
STS24	Smoke Detector	Roof	Core 1	Green / Operational	1	N/A	N/A	N/A

ASSET DETAIL

Asset STS1

GREEN / OPERATIONAL

Control Panel

Reference: STS1

LOCATION / DETAILS

Asset ID / Reference: STS1**Building:** Demo building**Floor:** First**Area:** Stuart hall room**Asset Type:** Control Panel**Photos Attached:** 2

NOTES

No notes recorded.

ASSET PHOTOS



Demo control panel



Demo battery backup

ASSET DETAIL

Asset STS2

GREEN / OPERATIONAL

Break Glass

Reference: STS2


LOCATION / DETAILS

Asset ID / Reference: STS2**Building:** Demo building**Floor:** Second**Area:** Core 1 lobby**Asset Type:** Break Glass**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo break glass unit

ASSET DETAIL

Asset STS3

GREEN / OPERATIONAL

AOV Damper

Reference: STS3

LOCATION / DETAILS

Asset ID / Reference: STS3**Building:** Demo building**Floor:** Second**Area:** Core 1 lobby**Asset Type:** AOV Damper**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo aov / smoke vent

ASSET DETAIL

Asset STS4

GREEN / OPERATIONAL

AOV Damper

Reference: STS4

LOCATION / DETAILS

Asset ID / Reference: STS4**Building:** Demo building**Floor:** Second**Area:** Core 1 head of stairs**Asset Type:** AOV Damper**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo aov / smoke vent

ASSET DETAIL

Asset STS5

GREEN / OPERATIONAL

AOV Damper

Reference: STS5

LOCATION / DETAILS

Asset ID / Reference: STS5**Building:** Demo building**Floor:** First**Area:** Core 1 lobby**Asset Type:** AOV Damper**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo aov / smoke vent

ASSET DETAIL

Asset STS6

GREEN / OPERATIONAL

Break Glass

Reference: STS6


LOCATION / DETAILS

Asset ID / Reference: STS6**Building:** Demo building**Floor:** First**Area:** Core 1 lobby**Asset Type:** Break Glass**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo break glass unit

ASSET DETAIL

Asset STS7

GREEN / OPERATIONAL

Break Glass

Reference: STS7


LOCATION / DETAILS

Asset ID / Reference: STS7**Building:** Demo building**Floor:** Ground**Area:** Core 1 lobby**Asset Type:** Break Glass**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo break glass unit

ASSET DETAIL

Asset STS8

GREEN / OPERATIONAL

AOV Damper

Reference: STS8

LOCATION / DETAILS

Asset ID / Reference: STS8**Building:** Demo building**Floor:** Ground**Area:** Core 1 lobby**Asset Type:** AOV Damper**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo aov / smoke vent

ASSET DETAIL

Asset STS9

GREEN / OPERATIONAL**Fan**

Reference: STS9

LOCATION / DETAILS**Asset ID / Reference:** STS9**Building:** Demo building**Floor:** Roof**Area:** Core 1**Asset Type:** Fan**Photos Attached:** 1**NOTES**

No notes recorded.

ASSET PHOTOS

Demo extract fan

ASSET DETAIL

Asset STS10

GREEN / OPERATIONAL**Fan**

Reference: STS10

LOCATION / DETAILS**Asset ID / Reference:** STS10**Building:** Demo building**Floor:** Roof**Area:** Core 1**Asset Type:** Fan**Photos Attached:** 1**NOTES**

No notes recorded.

ASSET PHOTOS

Demo extract fan

ASSET DETAIL

Asset STS11

GREEN / OPERATIONAL

Control Panel

Reference: STS11

LOCATION / DETAILS

Asset ID / Reference: STS11**Building:** Demo building**Floor:** Second**Area:** Core 2 stairs**Asset Type:** Control Panel**Photos Attached:** 2

NOTES

No notes recorded.

ASSET PHOTOS



Demo control panel



Demo battery backup

ASSET DETAIL

Asset STS12

GREEN / OPERATIONAL**AOV Damper**

Reference: STS12

LOCATION / DETAILS**Asset ID / Reference:** STS12**Building:** Demo building**Floor:** Second**Area:** Core 2 head of stairs**Asset Type:** AOV Damper**Photos Attached:** 1**NOTES**

No notes recorded.

ASSET PHOTOS**Demo aov / smoke vent**

ASSET DETAIL

Asset STS13

GREEN / OPERATIONAL

Break Glass

Reference: STS13


LOCATION / DETAILS

Asset ID / Reference: STS13**Building:** Demo building**Floor:** Second**Area:** Core 2 lobby**Asset Type:** Break Glass**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo break glass unit

ASSET DETAIL

Asset STS14

GREEN / OPERATIONAL**AOV Damper**

Reference: STS14

LOCATION / DETAILS**Asset ID / Reference:** STS14**Building:** Demo building**Floor:** Second**Area:** Core 2 lobby**Asset Type:** AOV Damper**Photos Attached:** 1**NOTES**

No notes recorded.

ASSET PHOTOS**Demo aov / smoke vent**

ASSET DETAIL

Asset STS15

GREEN / OPERATIONAL

AOV Damper

Reference: STS15

LOCATION / DETAILS

Asset ID / Reference: STS15**Building:** Demo building**Floor:** First**Area:** Core 2 stairs**Asset Type:** AOV Damper**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo aov / smoke vent

ASSET DETAIL

Asset STS16

GREEN / OPERATIONAL**AOV Damper**

Reference: STS16

LOCATION / DETAILS**Asset ID / Reference:** STS16**Building:** Demo building**Floor:** First**Area:** Core 2 lobby**Asset Type:** AOV Damper**Photos Attached:** 1**NOTES**

No notes recorded.

ASSET PHOTOS**Demo aov / smoke vent**

ASSET DETAIL

Asset STS17

GREEN / OPERATIONAL

Break Glass

Reference: STS17


LOCATION / DETAILS

Asset ID / Reference: STS17**Building:** Demo building**Floor:** First**Area:** Core 2 lobby**Asset Type:** Break Glass**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo break glass unit

ASSET DETAIL

Asset STS18

GREEN / OPERATIONAL

AOV Damper

Reference: STS18

LOCATION / DETAILS

Asset ID / Reference: STS18**Building:** Demo building**Floor:** Ground**Area:** Core 2 lobby**Asset Type:** AOV Damper**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS

**Demo aov / smoke vent**

ASSET DETAIL

Asset STS19

GREEN / OPERATIONAL

Break Glass

Reference: STS19


LOCATION / DETAILS

Asset ID / Reference: STS19**Building:** Demo building**Floor:** Ground**Area:** Core 2 lobby**Asset Type:** Break Glass**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo break glass unit

ASSET DETAIL

Asset STS20

GREEN / OPERATIONAL**AOV Damper**

Reference: STS20

LOCATION / DETAILS**Asset ID / Reference:** STS20**Building:** Demo building**Floor:** Second**Area:** Core 1 head of stairs**Asset Type:** AOV Damper**Photos Attached:** 1**NOTES**

No notes recorded.

ASSET PHOTOS**Demo aov / smoke vent**

ASSET DETAIL

Asset STS21

GREEN / OPERATIONAL

Damper

Reference: STS21

LOCATION / DETAILS

Asset ID / Reference: STS21**Building:** Demo building**Floor:** Roof**Area:** Core 1**Asset Type:** Damper**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo aov / smoke vent

ASSET DETAIL

Asset STS22

GREEN / OPERATIONAL

Damper

Reference: STS22

LOCATION / DETAILS

Asset ID / Reference: STS22**Building:** Demo building**Floor:** Roof**Area:** Core 1**Asset Type:** Damper**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo aov / smoke vent

ASSET DETAIL

Asset STS23

GREEN / OPERATIONAL

Smoke Detector

Reference: STS23

LOCATION / DETAILS

Asset ID / Reference: STS23**Building:** Demo building**Floor:** Roof**Area:** Core 1**Asset Type:** Smoke Detector**Photos Attached:** 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo smoke detector

ASSET DETAIL

Asset STS24

GREEN / OPERATIONAL

Smoke Detector

Reference: STS24

LOCATION / DETAILS

Asset ID / Reference: STS24

Building: Demo building

Floor: Roof

Area: Core 1

Asset Type: Smoke Detector

Photos Attached: 1

NOTES

No notes recorded.

ASSET PHOTOS



Demo smoke detector